


FIG. 2

Gap condition: L1>L2


3/23



Front View of the Balk Ring


FIG. 3


4/23





Front View of the Synchro Hub

FIG. 4















FIG. 9

View A






Gap condition: L3>L4



-16. 12







FIG. 14






FIG. 16





FIG. 17






FIG. 19




FIG. 20

View A

Gap condition:L5>L6





FIG. 21






FIG. 23